The Govmark Organization, Inc.

96-D Allen Boulevard
Farmingdale, New York 11735-5626 USA
Tel. +1 (631) 293-8944 Fax +1 (631) 293-8956
e-mail: info@govmark.com

Page 1

Received: 06/04/2013	Completed: 06/05/2013	Letter: T	BG	P.O.#: AN00204398	Test Report #:	2-97198-0-

Client's Identification	Dickson Orchestra # U105. Lot #: 895061201305. Gold.

Tested For: Benji Bagwell
Glen Raven
4665 Liberty Highway
Anderson, SC 29621

Key Test: CA 117 E   135

Tel: 1-(864)-716-4422   **Ext:**
Fax: 1-(864)-225-2948

```
ec: David Buffington, email: dbuffington@glenraven.com

      CA 117: LE 2000; R 7/09; V 7/09              PC: .5H+.5H        DL/jd

TEST PERFORMED:  California Technical Bulletin 117 (March 2000) Section E Upholstery Fabrics

RESULTS:          LENGTH                      WIDTH
                  Burning Time                Burning Time
Specimen          (seconds)         Specimen  (seconds)
--------          -----------       --------  -----------
#1  Face             DNI            #6   Face     DNI
#2  Face             DNI            #7   Face     DNI
#3  Face             DNI            #8   Back     DNI
#4  Back             DNI            #9   Back     DNI
#5  Back             DNI            #10  Back     DNI
                  -----------                 -----------
    Avg:                               Avg:

NOTE:  This is a minimal flammability test to screen out highly flammable materials.

REMARKS:  None.

ACCEPTANCE CRITERIA:  Shall meet Class I of CS 191-53 --

                              Minimum Average Burning Time (Flame Spread)
                              -------------------------------------------
  [x] Plain Surface Materials:     3.5 Seconds or No Recordable Burning Time
  [ ] Raised Surface Materials:    7.0 Seconds or No Recordable Burning Time

ABBREVIATIONS OF "NO RECORDABLE BURNING TIME" CATEGORIES:

  DNI = Did not ignite when exposed to test ignition source.
  IBE = Ignited but extinguished before burning through stopcord.
  SF  = Surface flash only; stopcord not burned & no burning/charring/fusing of the base fabric.
  TSF = Timed surface flash; stopcord burned, but no burning/charring/fusing of the base fabric.

CONCLUSION:  Based on the above Results and Acceptance Criteria, the item tested:

  [x] Complies;  [ ] Does not comply

CERTIFICATION:  I certify that the above results were obtained after testing specimens in accordance
with the procedures and equipment specified by California Technical Bulletin 117 (March 2000) Section E
Upholstery Fabrics.
```

JUN 07 2013

AUTHORIZED SIGNATURE
THE GOVMARK ORGANIZATION, INC. / ec

MS. PHYLLIS PETTIT   (Page 1 of 1)